


3 Keys to Success in Barcode Label Application


• Time



LIGHT GARMENTS
or FABRICS
10-12 Seconds



HEAVY GARMENTS
12-14 Seconds



• Temperature



TOP HEAT
380°-400° F 193°-204° C

BOTTOM HEAT
300°-330° F 148°-165° C



• Pressure




2" x 4" PLATEN
25 - 30 psi

3" x 5" PLATEN
50 - 60 psi

4" x 6" PLATEN
70 - 85 psi

3-1/4" x 5" GOOSENECK
55 - 65 psi



For more information on application, heat seal machine settings, trouble shooting:
see our website ipc-tags.com and click on 'Resources and Links' and then click on 'Application Specs for HT Labels'.

For ordering labels, prices, or more information contact Amber@ipc-tags.com
Customer Service: 817-714-8400 • Order Fax: (817) 887-1725 • Corporate (972) 822-0934